

Stop Use & Recall Notice

AE529ADJ/3AU 3M PROTECTA
Adjustable Shock Absorbing Webbing Lanyard

3M Australia Pty Limited

Building A, 1 Rivett Road North Ryde, NSW 2113

Phone: +61 2 9498 9333 Fax: +61 2 9498 9666 Web: 3M.com.au


Product Information: 136 136 ABN 90 000 100 096 Dear customers,

Re: PROTECTA Adjustable Shock Absorbing Webbing Lanyard AE529ADJ/3AU

3M Australia has identified a labelling/ marking issue with a small batch of lanyard assemblies, affecting a total quantity of 56 units. The labelling issue could result in the printed information on the label being misinterpreted according to AS 1891.5:2020 Personal equipment for work at height, Part 5: Manufacturing requirements for lanyard assemblies and pole straps.

As a result of internal reviews and consistent with our commitment to quality and safety, we are providing this Stop Use & Recall Notice for the batch of 56 units manufactured between FEB 8th, 2024 and APR 22nd, 2024 for the below part number:

AE529ADJ/3AU 70007928537 Protecta adj. lanyard 2m;
2x snap hooks





We are not aware of any accidents or injuries related to the use of these 3M PROTECTA Adjustable Shock Absorbing Webbing Lanyards. We have not received any customer complaints regarding this but have identified it through an internal review.


During an internal review, we found that a small number of certified AS 1891.5:2020 lanyard assemblies were incorrectly labelled.

Correct labelling according to AS 1891.5:2020

License no: BMP 750971



Incorrect labelling according AS 1891.5:2020



Specific Protecta lanyard assemblies with incorrect labelling and certified to AS 1891.5:2020 affected by this Stop Use & Product Recall Notice are listed below shown:

3M	part number	Lot number	Product description
70007928537	AE529ADJ/3AU	2405028006	Protecta adj.
			lanyard 2m;
			2x snap hooks

This Stop Use & Recall Notice does not affect any other lanyard assemblies certified to AS 1891.5:2020.

User/ Owners:

To determine if your lanyard assemblies are affected, please follow the steps listed below:

- Locate the part number and batch details on your lanyard assembly to determine if matches the affected product details above. If you determine your product if affected, remove from service and do not continue use.
- Please complete the enclosed "End User Stock Return Form" and return both the product & the form to the 3M distributor you purchased the product from.
- Your distributor will forward the form to 3M and 3M will arrange for your affected physical stock to be returned to 3M.
- Your distributor can issue a credit for all stock appropriately returned or offer a replacement.

Thank you in advance for your support and cooperation in reaching your customers with this information. 3M sincerely regrets any inconvenience caused.

Please contact our 3M Customer Service department at <u>3msupport.safety.au@mmm.com</u> for any required assistance 1800 245 002.

3M Fall Protection 1800 245 002